

Special Adjustment Index Pos. Motor Sw. Motor run sw. wire colors Orange/Green and Yellow should make before 100,000 reset cont. sw. wire colors Red/Blue and Green/White break. Std. 66	Special Adjustment Index Pos. Motor Sw. Motor run sw. wire colors Orange/Green and Yellow should make before 100,000 reset cont. sw. wire colors Red/Blue and Green/White break. Std. 66
--	--

Fonts used: Rockwell, Century
Size: 44x30mm

Std. 66 Motor Switch label confirmed.
If you have more labels like this, please send me an image.

Enjoy and have fun,
Peter

www.inkochnito.nl

If you like my work, please send me a donation via PayPal.